

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Sacramento Maintenance Yard Cache Creek

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 North Levee	Left	11.69	09/04/2018 09/20/2018	Zach Jojola

LM Start		Rating **	A	Issue No.	2
LM End		Issue Type +	Ma	Location *	N/A
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Operations & Maintenance Manuals			°	°
DWR ID	DWR_ST0001_01_s_2013_2				
Comment Code					
Inspector Comment					
The Sacramento Maintenance Yard has copies of the O&M Manuals.					

No Photos

LM Start		Rating **	A	Issue No.	5
LM End		Issue Type +	Ma	Location *	N/A
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Emergency Supplies & Equipment			°	°
DWR ID	DWR_ST0001_01_s_2013_5				
Comment Code					
Inspector Comment					
The Sacramento Maintenance Yard maintains a stockpile of flood fight materials.					

No Photos

LM Start		Rating **	A	Issue No.	21
LM End		Issue Type +	Ma	Location *	N/A
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Flood Preparedness & Training			°	°
DWR ID	DWR_ST0001_01_s_2013_21				
Comment Code					
Inspector Comment					
The Sacramento Maintenance Yard remain current on their emergency response training and practices.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Sacramento Maintenance Yard Cache Creek

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 North Levee	Left	11.69	09/04/2018 09/20/2018	Zach Jojola

LM Start	2.07	Rating **	M	Issue No.	55
LM End	2.07	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			38.732415 °	38.732415 °
				-121.805731 °	-121.805731 °
DWR ID	DWR_ST0001_01_s_2018_55				
Comment Code					
PR : Prunings					
Inspector Comment					
Prunings on waterside slope.					

No Photos

LM Start	2.20	Rating **	M	Issue No.	81
LM End	2.20	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			38.733688 °	38.733688 °
				-121.804215 °	-121.804215 °
DWR ID	DWR_ST0001_01_s_2017_81				
Comment Code					
TR : Tree or limb					
Inspector Comment					
Dead tree stumps on waterside levee slope.					

Photo 1 of 1 : FA_2018_ST0001_259_81_20180904_00049.jpg



Dead tree stumps on waterside levee slope. Spring 2017.

LM Start	2.27	Rating **	M	Issue No.	37
LM End	2.27	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			38.733676 °	38.733676 °
				-121.802958 °	-121.802958 °
DWR ID	DWR_ST0001_01_f_2017_37				
Comment Code					
TR : Tree or limb					
Inspector Comment					
Wood pile on waterside hinge point.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Sacramento Maintenance Yard Cache Creek

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 North Levee	Left	11.69	09/04/2018 09/20/2018	Zach Jojola

LM Start	2.40	Rating **	C	Issue No.	31	
LM End		Issue Type +	Ma	Location *	WS	
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	2017 USACE Erosion Survey, DRAFT			38.733698 °		°
				-121.800508 °		°
DWR ID	DWR_ST0001_01_f _ 2018_31					
Comment Code						
Inspector Comment						
2017 Site ID: CHC 2.8 L						
Status: Repaired						
2017 Field Notes:						
Site History: 2006 - Large new failure. 2008 - Plans for repair currently in the design phase. 2010 - Planned setback levee by CA DWR, 60% design complete, construction planned for 2012. 2011 - Construction delayed to 2013 - 2014. 2016 - Site repaired with a setback levee by CA DWR.						

No Photos

LM Start	2.57	Rating **	A/W	Issue No.	30
LM End	2.61	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	2017 USACE Erosion Survey, DRAFT			38.732836°	38.732685°
				-121.797893°	-121.797154°
DWR ID	DWR_ST0001_01_f_2018_30				
Comment Code					
Inspector Comment					
2017 Site ID: CHC 2.4 L Status: Critical 2017 Field Notes: No observed change. Site History: Site identified as CRITICAL in 2002. 2006 - Currently constructing a setback levee. New failures present and extensive. Downstream end of the setback levee did not extend far enough. Upstream end was repaired. 2007 - DWR repaired with a setback levee, but the levee did not go far enough downstream. 2012 - New cracks observed. 2013 - Fresh erosion on upper bank.					
DWR Inspector Comment: No observed changes in erosion. Fall 2018.					

Photo 1 of 3 : FA_2018_ST0001_259_30_20180924_00072.jpg



View of erosion on the waterside toe road. Fall 2018.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	--	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Sacramento Maintenance Yard Cache Creek

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 North Levee	Left	11.69	09/04/2018 09/20/2018	Zach Jojola

LM Start	2.57	Rating **	A/W	Issue No.	30 (cont)
LM End	2.61	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	2017 USACE Erosion Survey, DRAFT			38.732836 °	38.732685 °
				-121.797893 °	-121.797154 °
DWR ID	DWR_ST0001_01_f_2018_30				
Comment Code					

Comment Code

Inspector Comment

2017 Site ID: CHC 2.4 L
Status: Critical
2017 Field Notes: No observed change.
Site History: Site identified as CRITICAL in 2002. 2006 - Currently constructing a setback levee. New failures present and extensive. Downstream end of the setback levee did not extend far enough. Upstream end was repaired. 2007 - DWR repaired with a setback levee, but the levee did not go far enough downstream. 2012 - New cracks observed. 2013 - Fresh erosion on upper bank.

DWR Inspector Comment: No observed changes in erosion. Fall 2018.

LM Start	2.57	Rating **	A/W	Issue No.	30 (cont)
LM End	2.61	Issue Type +	Ma	Location *	WS

Photo 2 of 3 : FA_2018_ST0001_259_30_20180924_00073.jpg



Additional view of the erosion, facing downstream. Fall 2018.

Photo 3 of 3 : FA_2018_ST0001_259_30_20181023_00033.jpg



USACE 2013 Photo #1

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Sacramento Maintenance Yard Cache Creek

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 North Levee	Left	11.69	09/04/2018 09/20/2018	Zach Jojola

LM Start	2.84	Rating **	A/W	Issue No.	62 (cont)	
LM End	2.84	Issue Type +	Ma	Location *	WS	
Category	Earthen Levee			GPS Latitude/Longitude		
				Start		End
Item	Erosion / Bank Caving			38.734514 °	38.734514 °	
				-121.793418 °	-121.793418 °	
DWR ID	DWR_ST0001_01_s_2018_62					
Comment Code						
E1 : Note and monitor erosion site.						
Inspector Comment						
Erosion on waterside berm and toe road.						

LM Start	2.84	Rating **	A/W	Issue No.	62 (cont)
LM End	2.84	Issue Type +	Ma	Location *	WS

Photo 4 of 5 : FA_2018_ST0001_259_62_20180904_00042.jpg



Additional view of erosion, looking northwest. Spring 2018.

Photo 5 of 5 : FA_2018_ST0001_259_62_20180904_00043.jpg



View of erosion from levee crown, facing Cache Creek. Fall 2018.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Sacramento Maintenance Yard Cache Creek

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 North Levee	Left	11.69	09/04/2018 09/20/2018	Zach Jojola

LM Start	3.48	Rating **	C	Issue No.	32
LM End	3.57	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	2017 USACE Erosion Survey, DRAFT			38.732941 °	38.731626 °
				-121.784965 °	-121.785231 °
DWR ID	DWR_ST0001_01_f_2018_32				
Comment Code					
Inspector Comment					
2017 Site ID: CHC 3.4 L					
Status: Repaired					
2017 Field Notes:					
Site History: 2006 - Some significant new erosion, especially fresh upper bank slumping. Still substantial berm. 2010 - Site extended downstream, some new erosion, heavily vegetated and hard to see. Planned setback levee by CA DWR, 60% design complete, construction planned for 2012. 2011 - Construction delayed to 2013 - 2014. 2016 - Site repaired with a setback levee by CA DWR.					

No Photos

LM Start	4.22	Rating **	A/W	Issue No.	34
LM End	4.23	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	2017 Storm Damage			38.727207 °	38.727187 °
				-121.775521 °	-121.775450 °
DWR ID	DWR_ST0001_01_f _ 2017_34				
Comment Code					
Inspector Comment					
Levee Evaluation Comments					
Description:					
Site ID No:249					
Site Designation:LMA-57					
Repair Type: Erosion					
Rating:Area of Concern					
Field Date:6/2/2017					
Notes: setback levee site; remaining berm greater than 86 feet, no section taken, photo only.					

Photo 1 of 3 : LEVAL_FA_2018_249_954.jpg



* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

Sacramento Maintenance Yard Cache Creek

A photograph showing a dirt road or path on the left, leading towards a line of trees. A yellow survey pole is stuck vertically in the ground on the right side of the road, near a small ditch or erosion. The ground is sandy and light-colored. The background features a dense line of green trees under a clear blue sky.Page 8 of 9

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Sacramento Maintenance Yard Cache Creek

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 North Levee	Left	11.69	09/04/2018 09/20/2018	Zach Jojola

LM Start	7.69	Rating **	M	Issue No.	29
LM End	7.69	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		38.729027°	38.729027°	
			-121.721683°	-121.721683°	
DWR ID	DWR_ST0001_01_s_2015_29				
Comment Code					
V4 : Elderberries are blocking visibility and flood fight capability.					
Inspector Comment					

No Photos

LM Start	10.01	Rating **	M	Issue No.	25
LM End	10.01	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Animal Control		38.710296°	38.710296°	
			-121.697480°	-121.697480°	
DWR ID	DWR_ST0001_01_f_2015_25				
Comment Code					
A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					
Inspector Comment					
Approximately 4 holes halfway down the waterside slope.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

Sacramento Maintenance Yard Cache Creek

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Sacramento Maintenance Yard Cache Creek

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 South Levee	Right	11.48	09/20/2018 09/21/2018	Zach Jojola

LM Start	1.68	Rating **	C	Issue No.	35
LM End	1.68	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			38.730596 °	38.730596 °
				-121.786041 °	-121.786041 °
DWR ID	DWR_ST0001_02_s_2018_35				
Comment Code					
A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					
Inspector Comment					
Multiple rodents holes baited by the Sac Yard on landside slope near pruning pile. Recommend backfilling and monitoring.					

No Photos

LM Start	2.61	Rating **	M	Issue No.	36
LM End	2.61	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.724457 °	38.724457 °
				-121.771757 °	-121.771757 °
DWR ID	DWR_ST0001_02_s_2017_36				
Comment Code					
V4 : Elderberries are blocking visibility and flood fight capability.					
Inspector Comment					
Trim elderberry bush on landside levee slope.					

No Photos

LM Start	3.53	Rating **	A/W	Issue No.	2
LM End	3.60	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	2017 USACE Erosion Survey, DRAFT			38.722138°	38.723294°
				-121.759736°	-121.759588°
DWR ID	DWR_ST0001_02_f_2018_2				
Comment Code					
Inspector Comment					
2017 Site ID: CHC 3.5 R					
Status: Eroding					
2017 Field Notes: Significant amount of debris along bank.					
Site History: 2010 - Large slump on the upper berm, a tree has recently slid down the slope. 2011 - Large slump and new erosion. 2012 - Slightly steeper slopes and cracks observed.					

Photo 1 of 1 : FA_2018_ST0001_260_2_20181023_00001.jpg



USACE 2013 Photo #1

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	--	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Sacramento Maintenance Yard Cache Creek

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 South Levee	Right	11.48	09/20/2018 09/21/2018	Zach Jojola

LM Start	3.60	Rating **	M	Issue No.	24
LM End	3.60	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			38.723229 °	38.723229 °
				-121.759521 °	-121.759521 °
DWR ID	DWR_ST0001_02_s_2018_24				
Comment Code					
PR : Prunings					
Inspector Comment					
Prunings on the waterside slope.					

No Photos

LM Start	4.27	Rating **	M	Issue No.	25	
LM End	4.27	Issue Type +	Ma	Location *	LS	
Category	Earthen Levee			GPS Latitude/Longitude		
				Start		End
Item	Encroachments			38.726237 °		38.726237 °
				-121.749889 °		-121.749889 °
DWR ID	DWR_ST0001_02_f_2017_25					
Comment Code						
PR : Prunings						
Inspector Comment						
Prunings on landside slope.						

No Photos

LM Start	4.42	Rating **	A/W	Issue No.	4
LM End	4.42	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			38.726840 °	38.726840 °
				-121.747228 °	-121.747228 °
DWR ID	DWR_ST0001_02_f_2016_4				
Comment Code					
E1 : Note and monitor erosion site.					
Inspector Comment					
Erosion on LS slope near levee toe. It does not appear to pose a significant threat. Recommend monitoring.					

Photo 1 of 1 : FA_2018_ST0001_260_4_20180904_00004.jpg



Erosion on LS levee slope toward the toe. Fall 2016.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	--	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Sacramento Maintenance Yard Cache Creek

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 East Training Levee of Cache Creek Settling Basin	Left	2.26	09/04/2018 09/04/2018	Zach Jojola

LM Start	0.09	Rating **	A	Issue No.	2
LM End	0.09	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.726454 °	38.726454 °
				-121.717031 °	-121.717031 °
DWR ID	DWR_ST0001_04_f_2018_2				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					
The Sacramento Maintenance Yard continues to manage the vegetation at an exceptional level.					

Photo 1 of 1 : FA_2018_ST0001_261_2_20180905_00008.jpg



View of the recently burned and dragged landside slope. Fall 2018.

LM Start	2.26	Rating **	M	Issue No.	1	
LM End	2.26	Issue Type +	Ma	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start		End
Item	2017 Storm Damage			38.695424 °		38.695253 °
				-121.715914 °		-121.715926 °
DWR ID	DWR_ST0001_04_f_2017_1					
Comment Code						
Inspector Comment						
Levee Evaluation Comments						
Description:						
Site ID No:250						
Site Designation:LMA-58						
Repair Type: Erosion						
Rating:Area of Concern						
Field Date:6/2/2017						
Notes: training levee end slope where it keys into channel /access ramp erosion. No change as of fall 2018 inspection.						

Photo 1 of 3 : LEVAL_FA_2018_250_962.jpg

*** Location**

LS : Land Side N/A : Not Applicable
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable N : Not Inspected/Rated
M : Minimally Acceptable C : Corrected
U : Unacceptable A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Sacramento Maintenance Yard Cache Creek

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 East Training Levee of Cache Creek Settling Basin	Left	2.26	09/04/2018 09/04/2018	Zach Jojola

LM Start	2.26	Rating **	M	Issue No.	1 (cont)	
LM End	2.26	Issue Type +	Ma	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start		End
Item	2017 Storm Damage			38.695424 °		38.695253 °
				-121.715914 °		-121.715926 °
DWR ID	DWR_ST0001_04_f_2017_1					
Comment Code						
Inspector Comment						
Levee Evaluation Comments						
Description:						
Site ID No:250						
Site Designation:LMA-58						
Repair Type: Erosion						
Rating:Area of Concern						
Field Date:6/2/2017						
Notes: training levee end slope where it keys into channel /access ramp erosion. No change as of fall 2018 inspection.						

LM Start	2.26	Rating **	M	Issue No.	1 (cont)
LM End	2.26	Issue Type +	Ma	Location *	

Photo 2 of 3 : LEVAL_FA_2018_250_964.jpg



Photo 3 of 3 : LEVAL_FA_2018_250_973.jpg



* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Sacramento Maintenance Yard Cache Creek

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 East Training Levee of Cache Creek Settling Basin	Left	2.26	09/04/2018 09/04/2018	Zach Jojola

LM Start	2.26	Rating **	A/W	Issue No.	3
LM End	2.26	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			38.695416 °	38.695416 °
				-121.715943 °	-121.715943 °
DWR ID	DWR_ST0001_04_s_2017_3				
Comment Code					
E2 : Schedule repair of erosion site prior to the next inspection.					
Inspector Comment					
Scour on waterside levee slope at end of Unit 04 levee. There is no visible active erosion at this time, however future high water events will likely cause further erosion into the levee prism.					

LM Start	2.26	Rating **	A/W	Issue No.	3 (cont)
LM End	2.26	Issue Type +	Ma	Location *	WS

Photo 1 of 4 : FA_2018_ST0001_261_3_20180904_00004.jpg



View of scour on waterside levee slope at the end of Unit 4. Spring 2018.

Photo 2 of 4 : FA_2018_ST0001_261_3_20180904_00005.jpg



View of newly scoured pond adjacent to the levee. Spring 2018.

LM Start	2.26	Rating **	A/W	Issue No.	3 (cont)
LM End	2.26	Issue Type +	Ma	Location *	WS

Photo 3 of 4 : FA_2018_ST0001_261_3_20180904_00006.jpg



View of scour at the end of the Training Levee. Ramp is inaccessible at this time. Fall 2017.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	---	--	---	--

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Sacramento Maintenance Yard Cache Creek

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 East Training Levee of Cache Creek Settling Basin	Left	2.26	09/04/2018 09/04/2018	Zach Jojola

LM Start	2.26	Rating **	A/W	Issue No.	3 (cont)	
LM End	2.26	Issue Type +	Ma	Location *	WS	
Category	Earthen Levee			GPS Latitude/Longitude		
				Start		End
Item	Erosion / Bank Caving			38.695416 °	38.695416 °	
				-121.715943 °	-121.715943 °	
DWR ID	DWR_ST0001_04_s_2017_3					
Comment Code						
E2 : Schedule repair of erosion site prior to the next inspection.						
Inspector Comment						
Scour on waterside levee slope at end of Unit 04 levee. There is no visible active erosion at this time, however future high water events will likely cause further erosion into the levee prism.						

Photo 4 of 4 : FA_2018_ST0001_261_3_20180904_00007.jpg



Scour on waterside levee slope at end of Unit 04 levee. Spring 2017.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---